



Sewer crossing for Manises airport  
230 m in clay and gravel.  
Hydroshield DN2500.  
Continues precise surveying  
measurements were made on the airport  
runway. The highest settlement  
measured was 3 mm.



- CLAY
- SAND
- BOULDERS
- ROCK
- UNDER WATER LEVEL
- GEOTECHNICAL CHARACTERISTICS

- ROAD
- TRAIN
- AIRPORT
- CITY
- OUTFALL
- MOUNTAIN
- CURVE
- CROSSINGS CHARACTERISTICS